LÁNG et al. Appln. No. 10/578,491 January 6, 2010

## **IN THE SPECIFICATION**

Page 9, after line 1 please insert the following new paragraph:

FIG. 2c, a perspective view of a coupling cuff;

Page 11, after line 8 please insert the following new paragraph:

FIG. 2c shows a side view of a coupling cuff 18. The coupling cuff 18 includes flanges 19 and 20, which are separated by a recessed portion 21. Flange 19 connects to motor 4, and flange 20 connects to the air-carrying conduits. Flanges 19 and 20 may abut against one or more shoulders in the foam body formed by wall sections 8b, 9b and/or 8c, 9c of the mold.